



140 North Port Road, Port Perry, Ontario, Canada, L9L 0B7
Tel.: 905-985-6111 | Fax: 905-985-7349 | E-Mail: info@hindle.com
WWW.HINDLE.COM

FEEL MORE POWER.

IMPORTANT NOTE: FLANGE SPRING TAB ALIGNMENT ON HONDA GROM/KAWASAKI Z125 PRO

Please check this important step on the flange installation on the 2014-2025 HONDA GROM 125/KAWASAKI Z125 PRO FULL SYSTEM:

The flange plate on the Grom/Z125 is moveable and must be placed the correct way, depending on the year and model of the bike. When installing the exhaust flange plate, **ensure that the spring hole is properly aligned with the spring tab on the exhaust primary so that the spring sits straight** between the spring tab and mounting point. If the spring is installed on an angle, it can place uneven tension on the spring tab. **Failure to improperly align the spring can cause** excessive stress on the tabs and welds, premature wear or breakage of the spring and/or potential major damage to the exhaust system. Before final tightening, **visually confirm that the spring is installed straight** and that the tab and mount are directly in line with one another. Adjust the positioning of the flange and flange plate to achieve proper alignment. *See Images below.*



CORRECT



INCORRECT



SPRING HOLE ON FLANGE PLATE. LINE UP DEPENDING ON LOCATION OF SPRING TAB ON EXHAUST PRIMARY



PLACE FLANGE PLATE IN CORRECT SPOT, SO THAT THE SPRING HOLE WILL LINE UP WITH THE SPRING TAB ON PRIMARY